HAER PA 2-DUQU, 30-

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

U.S. STEEL DUQUESNE WORKS, PRIMARY MILLS Duquesne Allegheny County Pennsylvania HAER No. PA-115-D

All photographs by Martin Stupich, 1989, unless otherwise noted.	
An overview history and inventory of individual structures on the	ž
Duquesne site can be found in the HABS/HAER collection at the	
Library of Congress under HAER No. PA-115.	

PA-115-D-1	LOOKING EAST AT SOAKING PIT RECUPERATORS NEAR THE WESTERN WALL OF THE PRIMARY MILL BUILDING.
PA-115-D-2	VIEW OF LOWEY HYDROPRESS GROUND INGOT STRIPPER IN THE PRIMARY MILL BUILDING, LOOKING EAST.
PA-115-D-3	ROW OF INGOT CARS AND INGOTS IN THE PRIMARY MILL BUILDING LOOKING EAST.
PA-115-D-4	SOUTHWARD OVERHEAD VIEW OF INGOT TRANSFER TRACKS AND INGOT BUGGY ADJACENT TO SOAKING PITS ON RIGHT, IN THE PRIMARY MILL BUILDING.
PA-115-D-5	VIEW OF MOTOR/WINCH DRUM ASSEMBLY FOR INGOT BUGGIES IN THE PRIMARY MILL BUILDING LOOKING SOUTH.
PA-115-D-6	LOOKING WEST IN PRIMARY MILL BUILDING AT SOAKING PITS.
PA-115-D-7	VIEW OF 46" X 110" BLOOMING AND SLABBING MILL ROLL HOUSING IN THE PRIMARY MILL BUILDING LOOKING EAST.
PA-115-D-8	TWO ROWS OF MOTOR GENERATOR SETS EXTENDING NORTHWARD IN THE MOTOR ROOM OF THE PRIMARY MILL.
PA-115-D-9	GENERAL NORTHEASTERN EXTERIOR VIEW OF THE MAIN ROLL SHOP.
PA-115-D-10	LOOKING SOUTHWEST AT THE 21" MILL INSPECTION BUILDING, WITH PATTERN STORAGE BUILDING ON THE RIGHT. (Jet Lowe)